


√ 6<sup>th</sup> Street & 3<sup>rd</sup> Ave Bus Stop – NE Corner (SunTran # 11852)

ADA accessibility Score: 4

Ridership: boardings = 100, total = 167

Issue(s): Stop does not have loading area, has gap between sidewalk and curb

Solution(s): fill gap between sidewalk and curb & fill gap between sidewalk and retaining wall to create space at least 8' deep x 5' wide (minimum) preferably replace existing sidewalk with new concrete loading pad 22' long x 12' wide x 6" deep – start @ existing bus stop sign



**Stop completed:** shelter pad built, and stop no longer has gap between curb and sidewalk. Accessible for all bus stop users.

